

MISSING COMPONENTS

Where Pitch Switch should be

Disintegrated Cut Off Switch

Shards of glass cover every surface

VG206D AFTER OVERHAUL

